

FIG 1 FIG 2 FIG 3







FIG 2



Si

FIG 3






FIG 4

FIG

I

SL

PR

SC

P





FIG 6






FIG 7




FIG 8




FIG 10

FIG 9





FIG 15

FABRICATE TWO-PART  
PADS 3

100

105

PLACE PROBES INTO CONTACT  
WITH BODY-REGION OF PADS



110

FIG 11

MAKE SOLDER CONNECTIONS  
TO HEAD-REGIONS OF PADS

FIG

11